




RCR201/5




1

RCR201/6




MAX 50° C

RCR201/56  
RCR201/56A




RCR201/56  
 █ █ COLOR GREEN  
 RCR201/56A  
 █ █ COLOR BLUE




RCR201/5  
RCR201/6

2




RCR201/5


4



RCR201/6




3



RCR201/5






RCR201/6

5



RCR201/6  
MAX 50° C

38° C





38

	<b>P</b> P bar	0,5 MIN	MAX 10	5 1	
	<b>T</b> T °C	MAX 80	65 45		


IISTR00201/5#--NEU REV3.02/2022

Not included / Non incluso / Non Inclus / Nie zawarty/ No incluido / Nao incluido

1





2





3

4




2




METTERE GRASSO  
PUT GREASE










3




4





www.grupponobili.it

**PRIMA DI INIZIARE / BEFORE STARTING**



**PULIZIA / CLEANING**

